

ADDRESS: 1825 South Bay Road



INTERPRETATION:

- The encroachment is believed to comprise a portion of the home's septic system.
- Considerable deforestation.

All overlays were completed by a licensed surveyor using boundary survey data and digital topographic maps (from 2019; 1:6,000 scale) from the City of Greater Sudbury.